4. DEFINITIONS

a. **Affected Emp** ployee whose job requires them to work in the area of a machine or pi t in which servicing or maintenance is being performed under lockout ose job requires them to work in an area in which such servicing or m eing performed.

b. **Authorized -** CFR 1926.32(d)) defines “Authorized person” as a perso approved or as mployer to perform a specific type of duty or duties o at a specific lo ons at the jobsite. The St. Norbert College Direct Facilities (or t will determine which employees have the r knowledge, sk

c. **Authorized E** machine or pi ized employee may service is performed on a machine or a piece of equipment which must be locked and/or tagged out.

d. **Capable of Being Locked Out** – An energy isolation device is capable of being locked out if it is designed with a hasp or other means of attachment where a lock can be attached, or if it has a locking mechanism built into it.

e. **Contract Employees** – Personnel working within St. Norbert College by virtue of a contract, who are performing jobs similar to College employees,

3. Assist the applicable departments with the development of specific procedural steps required for the lockout and/or tagout of equipment or machinery during service and maintenance activities.

4. Conduct periodic inspections of the department's lockout/tagout procedures.

5. Maintain a listing of all lockout authorized employees.

6. Facilitate and provide Lockout/Tagout supplies as needed or the means to direct them and to safely accomplish lockout procedures.

c. **Departmental Managers**

1. Ensure that an inventory of all College owned machinery and equipment that are serviced or maintained by employees within their area of responsibility is completed.

2. Ensure that specific lockout/tagout procedures are developed for machinery and equipment that are serviced or maintained by employees!

in charge of the project shall directly supervise the application and removal of lockout and/or tagout devices from machines and equipment.

There must be a lockout device present for each contractor working on the job. Contractors must supply their own devices that shall be approved by a Department Manager or their designee. The authorized department employee shall place their lockout “first on, last off”.

position.

Note: The key(s) to the authorized employee's lock(s) must remain with the employee or be properly locked in a "lockbox" for the duration of the job.

d. Attach a properly completed "Danger – Do Not Operate" tag to each lock. If a machine or piece of equipment will not accept a lockout device, properly completed warning tag(s) must be attached at the same location(s) that the lockout device(s) would have been placed.

e. The employee shall list their name, contact phone number and lockout date on the tag(s).

f. In addition to locking out and tagging power driven machinery or equipment at the motor sl iti

j. Uncord and plug connected equipment, the equipment shall be shut down, unplugged and a “Danger” tag and red lockout device with padlock attached to the equipment plug.

k. Only upon the completion of each of the aforementioned steps shall the machine or piece of equipment be deemed safe to work on and a “Zero-Energy Snt

the machine or equipment re-energized to test or position the machine, equipment, or component, the following actions must be taken:

a. Clear machine or equipment of tools and materials.

b. Ensure that employees are safely removed from the machine or equipment.

c. Remove applicable lockout/tagout devices.

d. Energize and proceed with testing or positioning.

e. De-energize all systems and reapply lockout or tagout devices.

11. GROUP LOCKOUT/TAGOUT

a. **Single Disconnect Device -** When work involves more than one employee from the same trade group or employees from multiple trade groups (e.g. electricians, riggers, mechanics, etc.), and a single disconnect device will affect the lockout, the following procedures should be followed:

   i. Each authorized employee in charge of a group shall fasten a multiple lockout adapter to the energy-isolating device on the machine or piece of equipment. The employee in charge of each group shall then attach their individually assigned lock to the multiple lockout adapter, and a “Danger – Do Not Operate” tag to their lock.

   ii. Additional employees with each group shall also attach a similar lock and tag to the multiple lockout adapter of the employee in charge of their respective trade group.

   iii. Only the employee in charge of that group shall remove any multiple lockout adapters, protecting a particular trade group, and only after all other employees in that group have removed their locks and tags.

b. **Multiple Disconnect Device -** When work involves one or more trade groups, and multiple disconnects or other isolation devices must be locked out at different locations, the following procedures shall be followed:

   i. Each specifically designated employee in charge of a trade group shall obtain the necessary number of extra locks.

   ii. Each employee in charge of a respective trade group shall attach their lock to each disconnect or other isolation device, (utilizing a multiple lockout adapter if necessary), “Danger – Do Not Operate” tags must then be attached to each lock.

   iii. Additional employees within each trade group shall attach a “Danger – Do Not Operate” tag to each lock of the tradesmen in charge of their respective trade group.

   iv. There shall be at least one lock, attached to each disconnect, for each trade group on the job. Each employee in charge of a trade group shall keep in their sole possession, the key to all locks affecting the lockout.